

ITV Bellows RAR Summary

Brian Freeman July 2015





Outline

- Downtimes
- Problem Description
- Cause
- Corrective Actions (completed during 2015 SAD)
- Pending Corrective Actions (not yet assigned)
- Summary





Bellows: Downtimes

- 5 separate downtimes for bellows failures.
 - 4 ITV bellows and 1 Faraday Cup 2 Bellows.
 - Total Downtimes:
 - ITV1L18/ ITV1L22:
 - ITV1L10:
 - ITV1L14:
 - IFY0L03:

33.16 hrs 4.48 hrs 2.45 hrs 4.3 hrs





Bellows: Downtimes Cont.

- Original ITV1L18/ ITV1L22 events => 33.16
 hrs => Prompted RAR investigation.
- Additional failures occurred during investigation, broadening the scope of the report.
- Grand Total of Lost Time = 44.4 hrs





Bellows: Problem Description

- Original Downtime on March 3, 2015 a pump cart was placed at 1L18.
- A few days later leak occurred again, this time ITV was suspected.
- VacSeal was applied to ITV1L18 bellows and then ITV1L22, and the viewers disabled in software.





Warm Region Girder







Problem Description Cont.

- In each of the Downtimes following, where ITV/ bellows was suspect they were sprayed with VacSeal
- Then disabled, by disconnecting power solenoid power.







Viewer Assembly







Viewer Assembly

Bellows with cover removed





Bellows Profile

- From JLAB Drawing #58432-C-0100 Rev A.
- Standard Bellows PN# 103-55-5-EE:
 - Stanless Steel
 - 60 Convolutions
 - All individually welded.

NOTES: UNLESS OTHERWISE SPECIFIED

ENERGY

 THE FOLLOWING C.E.B.A.F. SPECIFICATIONS APPLY BELLOWS SPECIFICATION FOR U.H.V. EQUIPTMENT: #11141-S-0105
 NOM. BELLOWS O.D. 1.030
 NOM. BELLOWS I.D. .550
 PLATE THICKNESS .003
 NO. OF CONVOLUTIONS 60
 DIM. A: EXTENDED LENGTH 3.73 COMPRESSED LENGTH 2.10
 STROKE 1.625

For more information on Bellows Data: See Standard Bellows Website <u>www.std-bellows.com</u>





Bellows: Cause

- Leaking ITV bellows, and FCup 2 bellows.
- This was confirmed during the first few weeks of the Summer 2015 SAD. Bellows were pulled and analyzed in the Vacuum lab.
- The cause was confirmed to be normal wear and aging bellows on ITV components.
- Manufacture of bellows, Standard Bellows, quotes a lifetime of 5000-10000 cycles at 1 ATM of differential pressure.





- Team interviewed past and present operations staff to estimate the number of cycles, because this information is not archived.
 - The Linac Viewers were used very differently than they are now, and got heavy use during initial CEBAF commissioning.
 - Estimates showed that we are over 5000 insertions of the Linac viewers.





Corrective Actions Completed

- Team verified that JLab specifications for UHV bellows (#11141S0105) provided by Mechanical Engineering was indeed used in past and present orders.
- Team verified that the stroke lengths called out in drawings were not exceeding 75% of the extended length of the bellows, which is called out in the above specification.





Corrective Actions Completed Cont.

- During the first few weeks of the Summer down a change was made in the process in which the bellows are swapped out.
- The above procedural change and the low cost of the part allow us to be able to replace both North and South Linac ITV bellows, as well as the FCup 2 bellows.
- **ALL** should be in working condition for the upcoming run.





Corrective Actions Completed Cont.

- Insertion of the the viewers are now archived.
 - Method for counting cycles.
 - Replacement could happen prior to failure.
 - Can now better estimate lifetime of bellows for other ITVs as well (*Arcs, Spreaders, and Recombiners*)





Pending Corrective Actions

- It is recommended that someone from the Mechanical Engineering Group be assigned as the Design Authority for mechanical parts.
- Assessments should be done on other insertables to understand lifetime of bellows. *(Harps, Insertable Dumps, etc...)*





Pending Corrective Actions Cont.

- Better define Engineering response and Control Room protocol to keep Downtime as low as possible.
 - Parallel Troubleshooting
 - Control Room Training





Future Corrective Action

• If one of the newly replaced bellows happens to develop a leak, a detailed material analysis should be performed *(Metallurgy)*.





Bellows: Summary

- All Linac ITV Bellows replaced, along with FCup 2.
- Functionality of viewers and Faraday Cup have been restored.
- Ability to count cycles in the future.
 - For collecting quantitative data about number of cycles.
 - Possibility of preemptive replacement of bellows prior to failure.





For more information....

- See full report at:
 - <u>http://opsweb.acc.jlab.</u>
 <u>org/CSUEApps/rerdb/?load=640</u>
- Viewer Bellows Replacement ATLis:
 - <u>http://devweb.acc.jlab.</u>
 <u>org/CSUEApps/atlis/task/15169</u>



