

Industrialization of E-XFEL string and module assembly at CEA- Saclay



CEA contribution

- CEA contributes to the E-XFEL Cold Linac construction through String Assembly (WP9), Module Assembly (WP3) and BPM (WP17)
- Accelerator Module Assembly (WP3-WP9) : assembly of 103 accelerator modules with 1 per week throughput ! operated by an industrial contractor on the Saclay site.

- ☐ Phase 1 : 2007-2008 TTC 2009
 - Preliminary study subcontracted
- ☐ Phase 2: 2009-2010 TTC 2011
 - Preparation of Infrastructure and Tooling
- ☐ Phase 3: 2010 – 2012 TTC2012
 - Pre-industrial study
 - Prototyping : Training and Commissioning at Saclay with XFEL Prototype Modules (PXFEL2 and PXFEL3)

⇒ leading to Restricted Call for Tender signed in July 2012
- ☐ Phase 4: July 2012→ Q1-2015 TTC 20xy
 - XFEL module assembly by industry operator


Phase 1 : Overview of the Assembly Buildings

Clean rooms

Assembly halls

Offices

Warehouse



XFel Village


Bldg 126 North
40x11 m²

Bldg 126 South
30x17 m²

Bldg 124 North
25x15 m²

Court
Yard


Phase 1 : Assembly Hall : Workstations



the XFEL Village

Phase 3: Pre-industrial study and Prototyping

- Ajilon was subcontracted to perform the pre-industrial study
 - Tools Definition
 - Assembly Procedures with the non mechanical operations
 - Schedule
 - PBS – EBOM
 - Risk Analysis
 - Interruption Scenarios
 - Inventory Management
 - List and implantation of Services and Fluid Distribution
 - Listing of Parts and Its Packaging
 - Description of Reception Process & Controls
 - Using experience gained at DESY




Phase 3: Pre-industrial study and **Prototyping**

- Get the « Factory » ready:
 - Implement the pre-industrial study
 - Check the infrastructures
 - Check the tools
 - Check the procedures
 - Train the CEA-IRFU team
 - Prepare all the documentation templates
 - Set-up the QA/QC and MBOM
 - Feedback from the assemblies
- Assembly of 3 cryomodules over 2 years (T0=august 2010) : PXFEL3_1, PXFEL2_1, PXFEL2_2

Phase 3 : Lessons from Assembly Prototyping

PXFEL3_1 PXFEL3_1 CMTB Test cavity tests:
Cavities gradient limits

all cavities except C7 are limited by the breakdown



- PXFEL3_1 : cavity 1 (FE) and cavity 8 (HL) do not reproduce their VT performances. The causes are not identified:
 - coupler contamination through common conditioning waveguide box ?
 - particulate contamination during string assembly ?
 - shocks during transport CEA-DESY: (4g on frame, 1g on cryomodule) + (2g on frame , 2g on CM) events ?


⇒ Still an open question

- PXFEL3_1 : cavity 7 HOM2 badly tuned :

⇒ a successful RF measurement and HOM tuning campaign took place on PXFEL2_2 cavity string during Week 18, with the help of DESY and AMTF colleagues.

Phase 3 : Lessons from Assembly prototyping

- PXFEL2_2:
 - Leak on cavity 6 helium vessel (isolating vac and He circuit)
 - No exchange at CEA because of time constrain for XM-3
 - Not full penetration welding between the cones and the cavity.
 - For serie production, full penetration welding



Leak rate on cavity AC121 rises to a value higher than 1 e-5mbar.l.s-1

Phase 3 : Lessons from Assembly prototyping


- PXFEL2_2:
 - In situ leak appeared at the leak test of the cavity string before shipping (acceptance criteria) :

- leak detection before roll-out 10^{-10} mbar.l.s-1
- leak rate $7.8 \cdot 10^{-8}$ mbar.l.s-1

- discovered on cavity 6 CF 16 PU MC leak
- under investigation at DESY
- Verification of the tightening on the coming couplers ?



Phase 3 : Acceptance Data Package



QA : Non Conformance Reports

Six NCR recorded for PXFEL2_2 string assembly / 14



PROJET XFEL

ETAT DES NON CONFORMITES - NON CONFORMANCE STATUS

NCR number	Model	Sub-assembly	Serial number	WS	MAJ /min	Date	Object	Corrective Action Status	Final Decision Date	Final Decision	Rédacteur
CEA-XFEL-RNC-11-011	PXFEL 2_2	Cavity	AC 147	Reception		08/12/2011	Orientation of the angle valve + pin of the HOM2 connector + vacuum above 10-5 mbar @ reception			quarantine	
CEA-XFEL-RNC-12-012	PXFEL 2_2	Cavities	AC150 & AC149	ISO 4 CC		10/02/2012	Water behind the flange of the elbow valve			use as is	
CEA-XFEL-RNC-12-013	PXFEL 2_2	Coupler	AC3C2	ISO 4 CC		20/02/2012	Coupler Antenna tilted			quarantine	
CEA-XFEL-RNC-12-014	PXFEL 2_2	Cavity	AC 150	ISO 4 CC		20/02/2012	Problem on cavity venting with UP34			use as is	C.Madec
CEA-XFEL-RNC-12-015	PXFEL 2_2	Couplers	CP3C45 & CP3C46	ISO 4 CC		22/02/2012	Remise à la PA rapide			use as is	S.Berry
CEA-XFEL-RNC-12-016	PXFEL 2_2	Coupler / cavity	CP3C57 / Z 162	ISO 4 CC		22/02/2012	Outils monté à l'envers / pour pouvoir démonter l'outillage nécessité d'enlever le coupleur.				B.Visentin

Irfu		European XFEL		NON CONFORMANCE REPORT / CHANGE REQUEST		Reference
EQUIPMENT:		coupler	SERIAL NUMBER:	AC3C2	FILLED OUT BY:	C. MADEC
Occurrence phase:		Control:	Reception:	Part	Integration level:	Workstation:
Manufacturing:		Acceptance:	Disassembly:	Equipment	Others:	
Design/validation:		Destockage:	Others:			
Integration:						
TITLE : Coupler antenna tilted						
DESCRIPTION :						
The coupler antenna is tilted in the horizontal plane, the coupler being in the support frame ready for connection to the cavity. The bellow holders were in position and tighten.						
Reference documents :						
TECHNICAL INVESTIGATIONS :				Responsible (s)		
The tilt of antenna axis was estimated at the half of the slot flange (for the leak test) i.e. 2.5 mm at the top of the antenna the tilt was about approximately 4 mm (cf. drawing page 4).						
CORRECTIVE ACTIONS (equipment concerned by NCR/CR) :				Responsible (s) :		CLASS :
On Friday 17th, we dismantled the coupler AC3C2 from the cavity Z141 and checked the antenna (pictures page 2, during disassembly). The coupler is now mounted back on a TWG.						
PREVENTIVE ACTIONS (further equipment) :				Responsible (s) :		MINOR :
DOCUMENTATION CHANGE :						
REPAIR :						
SCRAP :						
MODIFICATION :						
ACTION ON OTHER PRODUCT :						
Clearance for actions	Technical Manager	Quality assurance Manager	Project Manager			
Unit responsible of involved product :						
Upper level manager :						

Irfu		European XFEL		NON CONFORMANCE REPORT / CHANGE REQUEST		Reference
EQUIPMENT:		coupler	SERIAL NUMBER:	AC3C2	FILLED OUT BY:	C. MADEC
Occurrence phase:		Control:	Reception:	Part	Integration level:	Workstation:
Manufacturing:		Acceptance:	Disassembly:	Equipment	Others:	
Design/validation:		Destockage:	Others:			
Integration:						
TITLE : Coupler antenna tilted						
DESCRIPTION :						
The coupler antenna is tilted in the horizontal plane, the coupler being in the support frame ready for connection to the cavity. The bellow holders were in position and tighten.						
Reference documents :						
TECHNICAL INVESTIGATIONS :				Responsible (s)		
The tilt of antenna axis was estimated at the half of the slot flange (for the leak test) i.e. 2.5 mm at the top of the antenna the tilt was about approximately 4 mm (cf. drawing page 4).						
CORRECTIVE ACTIONS (equipment concerned by NCR/CR) :				Responsible (s) :		CLASS :
On Friday 17th, we dismantled the coupler AC3C2 from the cavity Z141 and checked the antenna (pictures page 2, during disassembly). The coupler is now mounted back on a TWG.						
PREVENTIVE ACTIONS (further equipment) :				Responsible (s) :		MINOR :
DOCUMENTATION CHANGE :						
REPAIR :						
SCRAP :						
MODIFICATION :						
ACTION ON OTHER PRODUCT :						
Clearance for actions	Technical Manager	Quality assurance Manager	Project Manager			
Unit responsible of involved product :						
Upper level manager :						



Example:

tilted coupler antenna

Phase 3 : MBOM

Component assembly			Component Reference									
ISO4 SA WS	ISO4 CC WS	ISO4 CC Workstation (Cavity+ColdCoupler)	EDMS-ID	Rev.	Reference dwg	Position	Quantity	q0SubType	F/N	temporary, modifiable, alternate		
Cavity String	Cavity with Cold Coupler	Cavity Full Equipped / Measured	D*905747, F	F	03L		1	assembly		1		
		Cavity Beamtube Blank Flange - Long Side	D*905747, F	F	03L	2	1 component		1	temporary		
		Cavity Beamtube Adapter Flange - Short Side	D*905747, F	F	03L	3	1 assembly		2	temporary		
		HOM Antenna	D*905747, F	F	03L	10	2 assembly		3			
		Pick-Up Antenna	D*905747, F	F	03L	12	1 assembly		4			
		High Q Fixed Antenna	D*905747, F	F	03L	15	1 assembly		5	temporary		
		Bellow Clamp										
		Coupler Cold Part Assembly										
		Test Wave Guide										
		Blind Flange for TWG										
		Aluminium Seal NW40										
		Coupler Cold Part Assembly Set										
		Threaded Rods M6x40										
		Washer d=6.4										
		CuNiSi Nut M6										
Q-pole unit assembly after transport												
Quad-BPM-Vat main body												
2Ph Pipe Flange Assembly (C)												
Dichtdeckel Verschaltungsbox (E)												
Beam Pipe Flange Assembly (A)												
Flange Assembly (B)												
Flange Assembly (D)												

It is collecting, recording, and archiving the complete mandatory fabrication information.

It is focused on the parts that are needed to assemble a CM at CEA. The MBOM also includes information about how the parts relate to each other, the inspection to be performed, the tests to be recorded, the assembly procedures, the documentation etc

Example of information : reference of the drawing, WP leader in charge of the supply serial number ... (54 columns, 500 lines)

→ configuration recording of each cryomodule

→ Arborecence documentaire de l'ADP sous EDMS (base documentaire géré par DESY)

MBOM on EDMS

Check Out From Team Submit Item Reports Bookmark History More Actions...

Physical Part , D00000000092239,A,1,1 , Item Info : Summary

Summary **BOM** Properties Related Items Next Steps All Versions

Related Items	Properties	Preview Image(s)															
<p>Is In Team Folder : 1 object</p> <table border="1"> <tr><th>Name</th></tr> <tr><td>CAV String 1: Physical Parts...</td></tr> </table> <p>Has Description : 3 objects</p> <table border="1"> <tr><th>Name</th></tr> <tr><td>Leak Check CoupAcc_0008 for CoupAcc_0008,A,1,1</td></tr> <tr><td>Template Coupler CP Reception A,1,1</td></tr> <tr><td>Template Coupler Final Leak Check A,1,1</td></tr> </table> <p>Is Instance of : 1 object</p> <table border="1"> <tr><th>Name</th></tr> <tr><td>Coupler_Accepted,A,1,1</td></tr> </table> <p>Has Fabrication Description : 4 objects</p> <table border="1"> <tr><th>Name</th></tr> <tr><td>Processing Instruction 03 REC CR 3,A,1,2</td></tr> <tr><td>Processing Instruction 09 SUP CR 9,A,1,2</td></tr> <tr><td>Processing Instruction 13 SUP CR 13,A,1,2</td></tr> <tr><td>Processing Instruction 45 BAC CR 45,A,1,2</td></tr> </table> <p>Is Used By Physical Part : 1 object</p> <table border="1"> <tr><th>Name</th></tr> <tr><td>CC_0008,A,1,1</td></tr> </table>	Name	CAV String 1: Physical Parts...	Name	Leak Check CoupAcc_0008 for CoupAcc_0008,A,1,1	Template Coupler CP Reception A,1,1	Template Coupler Final Leak Check A,1,1	Name	Coupler_Accepted,A,1,1	Name	Processing Instruction 03 REC CR 3,A,1,2	Processing Instruction 09 SUP CR 9,A,1,2	Processing Instruction 13 SUP CR 13,A,1,2	Processing Instruction 45 BAC CR 45,A,1,2	Name	CC_0008,A,1,1	<p>Description: Coupler_Accepted</p> <p>Serial Number: CoupAcc_0008</p> <p>Life Cycle State: Completed</p> <p>Access Scheme in Use: Team: WP09_CM-Assembly_Team</p> <p>Designated Access Scheme (Project): WP09_CM-Assembly</p> <p>Creator: mro_admin_1</p> <p>Work Status: Working</p> <p>Purpose:</p> <p>More Properties ...</p>	<p>Type (Instance of) Coupler_Accepted</p> <p>Serial Number CoupAcc_0008</p> <p>EDMS-ID D00000000092239</p>  
Name																	
CAV String 1: Physical Parts...																	
Name																	
Leak Check CoupAcc_0008 for CoupAcc_0008,A,1,1																	
Template Coupler CP Reception A,1,1																	
Template Coupler Final Leak Check A,1,1																	
Name																	
Coupler_Accepted,A,1,1																	
Name																	
Processing Instruction 03 REC CR 3,A,1,2																	
Processing Instruction 09 SUP CR 9,A,1,2																	
Processing Instruction 13 SUP CR 13,A,1,2																	
Processing Instruction 45 BAC CR 45,A,1,2																	
Name																	
CC_0008,A,1,1																	

Test report templates

Assembly procedure

QR Code identifying the part and linking it to the MBOM

Phases of the project

- ☐ Phase 1 : 2007-2008 TTC 2009
 - Preliminary study subcontracted
- ☐ Phase 2: 2009-2010 TTC 2011
 - Preparation of Infrastructure and Tooling
- ☐ Phase 3: 2010 – 2012 TTC2012
 - Pre-industrial study
 - Prototyping : Training and Commissioning at Saclay with XFEL Prototype Modules (PXFEL2 and PXFEL3)
 - ⇒ leading to Restricted Call for Tender signed in July 2012
- ☐ Phase 4: July 2012→ Q1-2015 TTC 20xy
 - XFEL module assembly by industry operator

Phase 4 : industrial phase

Contract for 103 CM integration awarded to ALSYOM in July 2012.

- The first phase (from Sept 17th, until Dec 2012), consists of :
 - the observation by ALSYOM of the assembly by CEA of the first pre-series cryomodule (XM-3)
 - the deployment of their industrial method based on the outputs of the prototyping
 - the set-up of the storage area,
 - the ERP (entreprise resource planning) parameterization
- The second phase (june 2013):
 - training of the company team attended by the CEA and DESY team on the assembly of the second and third pre-series modules XM-2 and XM-1.
- The third phase : From XM1 on (2013),
 - ALSYOM in charge of the series module assembly.
 - six months ramp-up period to reach the production rate of 1 CM per week.

Cost reductions

- Preindustrial studies
- Team training
- Cavity magnetic shields : proposed some closing improvements and new Cryophy™ material which was qualified on the CM prototypes.
- Precut and assembled multilayer blankets for the 2K and 70K superinsulation have been ordered: they facilitate the assembly and reduce its duration. Cryogenic loss measurements on the prototype modules qualified them for the series.
- Vacuum pumping system in the clean room : reduces time from 3/4h to 1/4h
- Hardware for the clean room assembly : savings in prep time
- Aligement software : savings in time, limit errors
- Rf bench : savings in time, limit errors
- Welding :
 - Welding leak tightness : duration reduced by using the CERN technology (only the detection of the welded area) : reduces pump and purge to lower He background
 - « Paint » test crack in the welds TUV vs Xrays of the weldings.



Conclusions

- Factory ready



- Cost reductions
- Alsym gets started – observation of XM-3

Thanks to

- 
- S. Berry, C. Cloué, JP Charrier, R. Legros, B. Visentin, O. Napoly, Y. Gasser, Y. Sauce, JL Perrin, A. Brasseur, M. Fontaine, C. Simon, D. Roudier, T. Vacher
 - Our colleagues from DESY (K.Jensch, S.Barbanotti, W.Maschmann ...) , INFN and other institutes for our collaborative work