KEK Crab Cavity Experience

- •Baseline design of the KEKB crab cavity
- •Test results before installation.

•Beam test

- (beam spectrum, Gas absorption, Maintenance) (LLRF oscillation, Kick the mass center)
- •Summary

Baseline design of KEKB crab cavity



Adjustment of Stop Band for Monopole Modes



Y.Morita (Mode identified by Cartesian coordinate)

Adjustment of Stop Band for Dipole Modes



Y.Morita (Mode identified by Cartesian coordinate)

Tapered coaxial coupler design

Coaxial coupler has several tapered sections. Decrease cut-off frequency (fc) for TE-mode propagation.



Stop band splitting design of the notch filter



Stop band

(H-V splitting)

509 MHz

650 MHz

570 MHz

TEM

TE(H)

TE(V)

Partitions

Previous design has a stop band at 630 MHz for TE mode. This band is close to the TE-1/4 λ mode. Stop band splitting notch filter has partitions in midplane to separate stop bands for horizontally polarized TE mode (650 MHz) and vertically polarized one (570 MHz).







Actual design of KEKB crab cavity



Surface treatment

The surface treatment was adopted the standard procedure. Almost tool and facility were available. (tesla cavity, KEKB scc)



Test Result Crab Cavity #LER



Specific luminosity with fewer number of bunches (200 bunches/beam)



Bunch number optimization

To make higher luminosity, the bunch number was optimized. 3.5 rf-bucket spacing was ordinary bunch pattern before install the crab cavities.

To change the fill pattern was required to make high luminosity.



Beam spectrum of 3.5 rf-backet spacing

-1

🚮 File Edit Window



FR Fill Pattern		
ile Name Read	EPoverl EB3.5Breaky	Water8_10ffset.dat
	Read File	ratoro_ronoutdat
ddress Offset:		0
ilot Bunch Address:		4839
emove Bunches: Addre	ss (or Address list)	
dd Buches: Address (o	r Address list)	
Make Train Gap		
umber of Trains		4
lumber of bunches / trai	n	200
	Generate & Display Pa	ttem
ile Name to be saved	FPoverLER.dat	
	Save LER Pattern	
ile name to be loaded	FPoverLER3.5BreakV	Water8_1Offset.dat
	Load LER Pattern	
ER Fill Pattern		
ile Name Read	FPoverHER3.5Break	Water8.dat
	Read File	
ddress Offset:		0
ilot Bunch Address:		4843
emove Bunches: Addre	ess (or Address list)	
dd Buches: Address (o	r Address list)	
Make Train Gap		
umber of Trains		16
umber of bunches / trai	n	60
	Generate & Display Pa	ttem
ile Name to be saved	EPoverHEB3.5Spacir	ng911 B reakWater8.dat
	Save HER Pattern	
ile name to be loaded	EPoverHEB3 5Spacin	ng11BreakWater8 dat
	Load HER Pattern	Igorrenoutratoronate
	Loan HEIT Fattern	
	Display	
lumber of Bunches: LER		1388
lumber of Bunches: HEF	1	911
lumber of Colliding Bunc	hes	0
•	Load LER&HER Patte	em

10/04/2007 22:48:22 Help -

Beam spectrum of 3.06 rf-backet spacing

🏭 File Edit Window

10/26/2007 09:30:33 <u>H</u>elp 👻



	Read File		
ldress Offset:		0	
lot Bunch Address:		4839	
eight Factor for Pilot Bu	inch:	1	
emove Bunches: Addre	ss (or Address list)		
ld Buches: Address (or	r Address list)		
Make Train Gap			
umber of Trains		4	
umber of bunches / train	1	200	
	Generate & Display	Pattern	
le Name to be saved	FPoverLER.dat		
	Save LER Patte	em	
e name to be loaded	FPoverLER3.06Bre	eakWater8.dat	
	Load LER Patte	em	
R Fill Patlern			
le Name Read	FPoverHER3.06Bre	eakWater8.dat	
	Read File		
ldress Offset:		0	
lot Bunch Address:		4843	
eight Factor for Pilot Bunch: 1			
emove Bunches: Addre	ss (or Address list)		
Id Buches: Address (or Address list)			
Make Train Gap			
umber of Trains		4	
Imper of punches / train	n	200	
	Generate & Display	Pattern	
e Name to be saved	FPoverHER3.06Br	eakWater8Pilot1.5.dat	
	Save HER Patt	em	
e name to be loaded	FPoverHER3.06Br	eakWater8Pilot1.5.dat	
	Load HER Patte	em	
R & HER			
	Display		
umber of Bunches: LER		1585	
umber of Bunches: HER		1585	
umber of Colliding Buncl	nes	1584	
	Load LER&HER Pa	attern	

FPoverLER3.06BreakWater8.dat

Beam spectrum of special pattern for machine study

IED Gill Pattom

🚮 File Edit Window



File Name Read	FPoverLER3.5Spaci	ng1383Bunches.dat
	Read File	
Address Offset:		0
Pilot Bunch Address:		4839
Remove Bunches: Addre	ess (or Address list)	
Add Buches: Address (o	r Address list)	
📕 Make Train Gap		
Number of Trains		16
Number of bunches / trai	n	18
	Generate & Display P	attem
File Name to be saved	FPoverLER16Trains281Bunches.dat	
	Save LER Patter	n
File name to be loaded	FPoverLER16Trains	281Bunches.dat
	Load LER Patter	n
HER Fill Pattern		
File Name Read	FPoverHER3.5Spac	ing1383Bunches.dat
	Read File	
Address Offset:		0
Pilot Bunch Address:		4843
Remove Bunches: Addre	ess (or Address list)	
Add Buches: Address (o	r Address list)	
📕 Make Train Gap		
Number of Trains		16
Number of bunches / trai	n	18
	Generate & Display P	attern
File Name to be saved	FPoverHER16Trains	s281Bunchesdat
	Save HER Patter	n
File name to be loaded	FPoverHER16Trains	s281Bunches.dat
	Load HER Patter	n
LER & HER		
	Display	
Number of Bunches: LER		281
Number of Bunches: HEF	2	281
Number of Colliding Bunc	hes	280
	Load LER&HER Pat	tem

04/09/2007 09:41:57 Help -

EditFillPattern on kcg-05.kek.jp:0.0

1

Beam spectrum

- The cavity vacuum was deteriorated, and the frequency of the cavity break down was increased just after change the fill pattern.
- If some specific mode was excited, the cavity vacuum was deteriorated even the cavity was detuned.

Maintenance

- Regular maintenance day was held every 2 weeks.
- If break down occur frequently, aging (commissioning) work was required.
 Sometimes additional aging was done at first year.
- If additional aging was not sufficiently effective, Cavity warm up was done to remove absorbed gases. (The cavities were warmed up twice in first 2 months)

Oscillation of high-current crabbing beams



- A large-amplitude oscillation was observed in high-current crabcrossing operation in June.
 - It caused unstable collision, short beam life time and luminosity degradation.
 - Crab amplitude and phase were modulated at 540 Hz. Horizontal oscillation of beams was also observed at the same frequency.
 - None of the beam orbit feedback systems is responsible, since their time constants are 1 to 20 sec, much slower than the oscillation.
 - The oscillation occurred when the LER tuning phase migrated to the positive side. This gave us a hint to understand the phenomena.

A remedy for the oscillation was found



Dependence on the crab phase and tuning phase. Beam current was 1150 mA (LER) and 620 mA (HER).

Observations at a machine study

- The oscillation occurred only with high-current colliding beams: it never occurred with a single beam, even at a high current.
- Both beams oscillates coherently.
- The threshold for the oscillation is dependent on the crab phase and tuning phase (see left).

Cause and remedy

- We concluded that the oscillation is caused by beam loading on crab cavities together with beam-beam force at the IP (see, next slide).
- We found that it can be avoided by shifting the crabbing phase by +10° and controlling the tuning offset angle appropriately.

Possible mechanism of the oscillation



Crab cavity operation (K. Akai)

13th KEKB Accelerator Review Committee

21

Reachable kick voltage

2

	HER	LER	
Vertical test	2.0	2.8	Limited by RF power supply.
	Ļ	Ļ	
Horizontal test	1.8	1.9	
	Ļ	Ļ	
Just after install	1.4	1.45	
		Ļ	
After 1 mounth	Ļ	1.0	LER Voltage suddenly
		\downarrow	dropped after a big quench.
After 3 years	1.7	1.3	LER Voltage gradually recovered.

Uncontrolled RF kicks beam mass center.

- Accidental beam turbulence was observed by bunch by bunch feedback system.
- Slow phase error makes COD.
- Fast phase error makes free oscillation.

Yellow :Klystron output power Blue :Pick up power(∞Vc2) Purple :Cavity phase Green :Beam current



When LLRF feedback was oscillated, corresponding displacement was observed.

Beam displacement corresponding phase error was observed.



In this case, the beam was not aborted after turn off the RF. After turned off the RF power for crab cavity, a horizontal oscillation was started. And it seems decaying. Finally, the beam was aborted due to discharge caused by the beam induced field. The beam survived for 2msec after turned off the RF.

4100

Yellow	:Klystron output power
Blue	:Pick up power(∝Vc2)
Purple	:Cavity phase
Green	:Beam current

- Yellow :Klystron output power
- Blue :Pick up power(∞ Vc2)
- Purple :Cavity phase
- Green :Beam current

The expected decay time of stored energy was 65 μ sec. (130 μ sec for cavity voltage) The LER beam was aborted by intentional abort request.



To stop the RF power makes turbulence.



In this case, RF power was stopped manually.

RF input coupler exposed big traveling wave RF power at that time, and it caused discharge phenomena.



RF trip rate of crab cavities



The averages of the RF trip rate during whole operation period were 1.3 and 0.5 per day for HER and for LER respectively.

Summary

- In KEKB, Crabing mode is not the lowest mode. The lowest mode and higher order mode(HOM) dumping was required. It makes the cavity system complicated.
- The KEKB crab cavity system have many parasitic mode (i.e. HOM related coaxial coupler that is the lowest mode and higher order mode dumper and frequency tuner). HOM was sometimes excited by beams. It deteriorated the vacuum and cause some discharge phenomena.
- When reachable voltage was dropped, removing the absorbed gases was effective by regular aging effort or system warming up.
- An oscillation of RF feedback system was observed at high beam current operation. It was made by interaction of RF control system through the beambeam force. It could be suppressed by adjusting cavity control parameter (i.e. tuning offset and crabing phase).
- Crabing phase error makes COD.
- When the crab cavity RF turns off, uncontrolled RF may be caused free oscillation.
- RF trip rate of crab cavity was decreased day by day.

Operating condition of crab cavity



H. Koiso, A. Morita

